

Dismantle Receive Note



DRID2607270071

Receive WH: ID XLS PLB

Receive WH Address:

Jalan Palembang Tanjung api - api Kec Talang

ASN:

DRID2607270071

Project 56A0R9P

Project Name:

Kelapa Banvuasin

ASN Type:

Dismantle Return

Code:

ETA: 2026-07-30

ASN Remark:

Inbound Date:

Site Code	DU Code	Subcon	Material Category	Material Model	Item Code	Item Name	Item Description	Reuse Type	Test Method	Qty	UOM	Received Qty	Picked Qty	Integrated SN	Received SN	Weight (KG)	Volume (CBM)	Remarks
SUM-LA-BDL 0638	SUM-LA-BDL 0638_MOCN_WLU	PT. Poca Jaringan Solusi	RAN	SFP	2527159	SFP 10G+1.4Km	SFP 10G+1.4Km	Resale	Others	2	PCS	✓						
SUM-LA-BDL 0638	SUM-LA-BDL 0638_MOCN_WLU	PT. Poca Jaringan Solusi	RAN	RRU 3938 900M	2509826	RRU 3938 900	RRU 3938 900	Resale	Others	2	PCS	✓						
SUM-LA-BDL 0638	SUM-LA-BDL 0638_MOCN_WLU	PT. Poca Jaringan Solusi	RAN	SFP	2509045	TRANSCEIVER: R:RTN OPTIC SFP 6.144G LC S	TRANSCEIVER: R:RTN OPTIC SFP 6.144G LC, SM.	Reusable	Others	6	PCS	✓						
SUM-LA-BDL 0638	SUM-LA-BDL 0638_MOCN_WLU	PT. Poca Jaringan Solusi	Cable		2084259	CABLE, ELECTRICAL: 2X18MM2 TWISTED.	CABLE, ELECTRICAL: 2X18MM2 TWISTED	Scrap	Others	150	M	X	Lacking					
SUM-LA-BDL 0638	SUM-LA-BDL 0638_MOCN_WLU	PT. Poca Jaringan Solusi	RAN	Optic Cable	2526960	Optical Cable 60m Conn LC-LC	Optical Cable 60m Conn LC-LC	Scrap	Others	6	PCS	✓						
SUM-LA-BDL 0638	SUM-LA-BDL 0638_MOCN_WLU	PT. Poca Jaringan Solusi	RAN	RRU 3952 1800&2100M	2508089	RRU 3952 1800&2100	RRU 3952 1800&2100	Resale	Others	2	PCS	✓	AAU 3911					
SUM-LA-BDL 0638	SUM-LA-BDL 0638_MOCN_WLU	PT. Poca Jaringan Solusi	RAN	AAU 3911	2508191	AAU 3911	AAU 3911	Resale	Others	1	PCS	✓	F					
SUM-LA-BDL 0638	SUM-LA-BDL 0638_MOCN_WLU	PT. Poca Jaringan Solusi	RAN	RRU 5865 1800M	2519640	RRU 5865 1800	RRU 5865 1800	Reusable	Others	1	PCS	✓	Faulty NO connector + NO bracket.					

Total Volume (CBM) 0

Total Weight (KG) 0

Is there any shortage, damage, discrepancy?

No ☐ Yes ☐

If Yes, Please describe the problem.

Delivered by:

Signature:

Date:

Checked by:

Signature:

Date:

Received by:

Signature:

Date:



SUM-LA-BDL-0638											
All List Material											
No.	Tower ID	SOW (Dismantle / Keep / New Material)	SAP Number HANA	Material Description	Quantity	UoM	Material Condition		Color Material (Red, Yellow, Green)	Remark	SUB-GROUP
							Good & Complet	Damage d/			
1	SUM-LA-BDL-0638	Dismantle	2507784	BBU3900	X 1	Pcs			Yellow	Phase 1	BBU
2	SUM-LA-BDL-0638	Dismantle	2507780	UMPTb1	X 1	Pcs			Yellow	Phase 1	Module BBU
3	SUM-LA-BDL-0638	Dismantle	2506926	U88Pd3	X 2	Pcs			Yellow	Phase 1	Module BBU
4	SUM-LA-BDL-0638	Dismantle	2509826	RRU 3938 900 Include Connector & Bracket	✓ 2	Pcs			Yellow	Phase 1	RRU
5	SUM-LA-BDL-0638	Dismantle	2519640	RRU 5865 1800 Include Connector & Bracket	✓ 1	Pcs			Green	Phase 1	RRU
6	SUM-LA-BDL-0638	Dismantle	2508089	RRU 3952 1800&2100 Include Connector & Bracket	✓ 2	Pcs			Yellow	Phase 1	RRU
7	SUM-LA-BDL-0638	Dismantle	2529116	Power Cable	X 46	Meter			Red	Phase 1	Cable
8	SUM-LA-BDL-0638	Dismantle	2526960	Optical Cable	✓ 6	Pcs			Red	Phase 1	Optic Cable
9	SUM-LA-BDL-0638	Dismantle	2500977	JUMPER_RF	X 1	Pcs			Red	Phase 1	RF Jumper
10	SUM-LA-BDL-0638	Dismantle	2509045	TRANSCEIVER:RTN OPTIC SFP 6.144G,LC,SM,>	✓ 1	Pcs			Green	Phase 1	SFP
11	SUM-LA-BDL-0638	Dismantle	2527159	SFP 10G+1.4Km	✓ 2	Pcs			Yellow	Phase 1	SFP
12	SUM-LA-BDL-0638	Dismantle	2531609	Power#Subrack# EPW30-48A#Huawei	X 1	Pcs			Yellow	Phase 1	SUBRACK
13	SUM-LA-BDL-0638	Dismantle	2508191	AAU 3911 Include Connector & Bracket	✓ 1	Pcs			Yellow	Phase 1	RRU


 pongki
 (Kris)


 27.07.24