

Dismantle Receive Note



DRID2603270067

Receive WH: ID XLS PLB

Project 56A0R9P

Code:

ETA: 2026-03-26

Receive WH Address: Jalan Palembang Ianjung api - api Kec Ialang
kelana Banuasari
Project Name: Indonesia XLSMART Network Consolidation Project

Asn Remark:

ASN: DRID2603270067

ASN Type: Dismantle Return

Inbound Date:

Site Code	DU Code	Subcon	Material Category	Material Model	Item Code	Item Name	Item Description	Reuse Type	Test Method	Qty	UOM	Received Qty	Picked Qty	Integrated SN	Received SN	Weight (KG)	Volume (CBM)	Remarks
SUM-SS-IDL-0135	SUM-SS-IDL-0135_MOCN_WLUB_LB	PT. Poca Jaringan Solusi	RAN	RF Jumper	2500977	RF Jumper 4.3-10 M to DM, 2M; RF Jumper DM to DM 5M- AISG	RF Jumper 4.3-10 M to DM, 2M; RF Jumper DM to DM 5M- AISG	Scrap	Others	6	PCS	✓						
SUM-SS-IDL-0135	SUM-SS-IDL-0135_MOCN_WLUB_LB	PT. Poca Jaringan Solusi	RAN	Optic Cable	2526960	Optical Cable 60m Conn LC-LC	Optical Cable 60m Conn LC-LC	Scrap	Others	3	PCS	✓						
SUM-SS-IDL-0135	SUM-SS-IDL-0135_MOCN_WLUB_LB	PT. Poca Jaringan Solusi	RAN	SFP	2509045	TRANSCEIVER: RTN OPTIC SFP 6.144G LC S	TRANSCEIVER: RTN OPTIC SFP 6.144G, LC, SM	Reusable	Others	6	PCS	✓						
SUM-SS-IDL-0135	SUM-SS-IDL-0135_MOCN_WLUB_LB	PT. Poca Jaringan Solusi	RAN	Cable Power	9001382	CABLE ELECTRICAL: 4X50 MM2 CU TWISTED PVC	CABLE ELECTRICAL: 4X50MM2 CU TWISTED PVC INSUL	Scrap	Others	120	M	✓						
SUM-SS-IDL-0135	SUM-SS-IDL-0135_MOCN_WLUB_LB	PT. Poca Jaringan Solusi	RAN	RRU 3938 900M	2509826	RRU 3938 900	RRU 3938 900	Resale	Others	3	PCS	✓						

Total Volume (CBM) 0

Total Weight (KG) 0

Is there any shortage, damage, discrepancy?

No ☐ Yes ☐

If Yes, Please describe the problem.

Delivered by: Refky

Signature:

Date:

27-03-26

Checked by: Leonardo

Signature:

Date:

27-maret-26

Received by: Leonardo

Signature:

Date:



SUM-SS-IDL-0135											
All List Material											
No.	Tower ID	SOW (Dismantle / Keep / New Material)	SAP Number HANA	Material Description	Quantity	UoM	Material Condition (Pls ✓ where applicable)		Color Material (Red, Yellow, Green)	Remark	SUB-GROUP
							Good & Complete	Damaged / Dented			
1	SUM-SS-IDL-0135	Dismantle	2509826	RRU 3918 900 Include Connector & Bracket	3	Pcs			Yellow	phase 2	RRU
2	SUM-SS-IDL-0135	Dismantle	2517203	RRU 5909 900 Include Connector & Bracket	3	Pcs			Yellow	Phase 2	RRU
3	SUM-SS-IDL-0135	Dismantle	2529116	Power Cable	3	Meter			Red	phase 2	Cable
4	SUM-SS-IDL-0135	Dismantle	2526960	Optical Cable	3	Pcs			Red	phase 2	Optic Cable
5	SUM-SS-IDL-0135	Dismantle	2500977	JUMPER_RF	3	Pcs			Red	phase 2	RF Jumper
6	SUM-SS-IDL-0135	Dismantle	2527159	SFP 10G+1.4Km	3	Pcs			Yellow	Phase 2	SFP
7	SUM-SS-IDL-0135	Dismantle	2509045	TRANSCEIVER RTN OPTIC SFP 6.144G, LC, SM, >	3	Pcs			Green	phase 2	SFP
8	SUM-SS-IDL-0135	Dismantle	2519574	EATON APR 48 ES	3	Pcs			Green	phase 1	Rectifier
9	SUM-SS-IDL-0135	Dismantle	2504420	HARDWARE: SUBRACK & INSTALLATION MATERI	3	Pcs			Yellow	hase 1 : only subrack (cabinet reuse/keep	Subrack

Replay
27-03-26



No Document	TSSR-50462				
RTL		Tower ID	SUM-SS-IDL-0135	Site ID	SUM-SS-IDL-0135
Site Name	Indralaya	Site Topology	HUT	Approved	Anton Situmorang
Indoor / Outdoor	Indoor	FLM Cluster	INDRALAYA XL	Morphology	RURAL
Site Type	Macro	Project Name	MOCN	Province	Sumatera Selatan
Kabupaten	Ogan Ilir	Kecamatan	Indralaya Utara	Latitude	-3.2096875
Longitude	104.6456875	Zona	2_South Sumatera	Date Dismantle	2025-09-18
Vendor	Huawei	Date TSSR	2025-09-11 18:32:18	Approve Date	2025-09-16 10:25:02
LDM By	HWI.Wahyuni Rizky Perdani	LDM Date	2025-09-16 02:34:36	Plan Dismantle	2025-09-02

No	Material Simplify	Material Detail	Description	Quantity LDM	UOM	Remark	Color
1	2504420	2504420	HARDWARE: SUBRACK & INSTALLATION MATERI	1	Pcs	#1	Yellow
2	2519574	2519574	EATON APR 48 ES	3	Pcs	#2	Green
Total				4			

Prepared by,

Approved by,

Reviewed by,

Checked by,

Received by,

HWI.Wahyuni Rizky Perdani

Anton Situmorang


 (Reky)


 (Leonard)
