

Dismantle Receive Note



DRID2604150325

Receive WH: ID XLS PLB

Project 56A0R9P

Code:

ETA: 2026-04-15

Receive WH Address: Jalan Palembang Tanjung api - api Kec Talang
kelapa Banvuasin
Project Name: Indonesia XLSMART Network Consolidation Project

Asn Remark:

ASN: DRID2604150325

ASN Type: Dismantle Return

Inbound Date:

Site Code	DU Code	Subcon	Material Category	Material Model	Item Code	Item Name	Item Description	Reuse Type	Test Method	Qty	UOM	Received Qty	Picked Qty	Integrated SN	Received SN	Weight (KG)	Volume (CBM)	Remarks
SUM-SS-IDL-0144	SUM-SS-IDL-0144_MOCN_WLUB_LB	PT. Poca Jaringan Solusi	RAN	RF Jumper	2500977	RF Jumper 4.3-10 M to DM, 2M; RF Jumper DM to DM 5M ATSC	RF Jumper 4.3-10 M to DM, 2M; RF Jumper DM to DM 5M ATSC	Scrap	Others	6	PCS	✓						
SUM-SS-IDL-0144	SUM-SS-IDL-0144_MOCN_WLUB_LB	PT. Poca Jaringan Solusi	RAN	RRU 3959 900M	2510265	RRU 3959 900	RRU 3959 900	Resale	Others	3	PCS	✓						
SUM-SS-IDL-0144	SUM-SS-IDL-0144_MOCN_WLUB_LB	PT. Poca Jaringan Solusi	RAN	Optic Cable	2526960	Optical Cable 60m Conn LC-LC	Optical Cable 60m Conn LC-LC	Scrap	Others	3	PCS	✓						
SUM-SS-IDL-0144	SUM-SS-IDL-0144_MOCN_WLUB_LB	PT. Poca Jaringan Solusi	RAN	Cable Power	9001382	CABLE ELECTRICAL: 4X50 MM2 CU TWISTED PVC INSUL	CABLE ELECTRICAL: 4X50 MM2 CU TWISTED PVC INSUL	Scrap	Others	150	M	✓						
SUM-SS-IDL-0144	SUM-SS-IDL-0144_MOCN_WLUB_LB	PT. Poca Jaringan Solusi	RAN	SFP	2509045	TRANSCEIVER: RTN OPTIC SFP 6.144G LC-S	TRANSCEIVER: RTN OPTIC SFP 6.144G, LC, SM,	Reusable	Others	6	PCS	✓						

Total Volume (CBM) 0

Total Weight (KG) 0

Is there any shortage, damage, discrepancy?

No ☐ Yes ☐

If Yes, Please describe the problem. _____

Delivered by: RPPK

Signature:

Date: 15-04-26

Checked by: Leonor PO


Signature:

Date: 15-04-26

Received by: Leonor PO

Signature:

Date: 15-04-26



SUM-SS-DL-0144											
All List Material											
No.	Tower ID	SOW (Dismantle / Keep / New Material)	SAP Number HANA	Material Description	Quantity	UoM	Material Condition (Pls y where applicable)		Color Material (Red, Yellow, Green)	Remark	SUB-GROUP
							Good & Complete	Damaged / Dented			
1	SUM-SS-DL-0144	Dismantle	2510265	RRU B959 900 Include Connector & Bracket	150	Pcs			Yellow	phase 2	RRU
2	SUM-SS-DL-0144	Dismantle	2529526	Power Cable	150	Meter			Red	phase 2	Cable
3	SUM-SS-DL-0144	Dismantle	2526960	Optical Cable	150	Pcs			Red	phase 2	Optic Cable
4	SUM-SS-DL-0144	Dismantle	2500977	JUMPER RF	150	Pcs			Red	phase 2	RF Jumper
5	SUM-SS-DL-0144	Dismantle	2509045	TRANSCEIVER RTN OPTIC SFP 8.144G LC SM	150	Pcs			Green	phase 2	SFP
6	SUM-SS-DL-0144	Dismantle	2523465	TONGYU TTB-809015/182017/182017DE-65f	150	Pcs			Yellow	phase 3	RF Antenna

July

1. Rejeki

15-04-26



No Document	TSSR-50405				
RTL		Tower ID	SUM-SS-IDL-0144	Site ID	SUM-SS-IDL-0144
Site Name	Buluh Mambo	Site Topology	HUT	Approved	Cecep Supriyadi
Indoor / Outdoor	Outdoor	FLM Cluster	INDRALAYA XL	Morphology	RURAL
Site Type	Macro	Project Name	MOCN	Province	Sumatera Selatan
Kabupaten	Ogan Ilir	Kecamatan	Indralaya Utara	Latitude	-3.1671875
Longitude	104.6868125	Zona	2_South Sumatera	Date Dismantle	2025-09-09
Vendor	Huawei	Date TSSR	2025-09-09 16:45:23	Approve Date	2025-09-09 16:57:39
LDM By	HWI.Wahyuni Rizky Perdani	LDM Date	2025-09-09 16:53:20	Plan Dismantle	2025-08-26

No	Material Simplify	Material Detail	Description	Quantity LDM	UOM	Remark	Color
1	2500977	2500977	JUMPER_RF	12	Pcs	Red#1	Red
2	2507780	2507780	UMPTb1	1	Pcs	Yellow#1	Yellow
3	2507784	2507784	BBU3900	1	Pcs	Yellow#2	Yellow
4	2523463	2523463	TONGYU_TTB-809015/182017/182017DE-65F	3	Pcs	Yellow#3	Yellow
Total				17			

Prepared by,

Approved by,

Reviewed by,

Checked by,


Received by,

HWI.Wahyuni Rizky Perdani

Cecep Supriyadi


(Rekey)


(Leonard)


(15-09-26)