

Dismantle Receive Note



Receive WH: ID XLS PLB
Project: 56A0R9P
Code:

Receive WH Address: Jalan Palembang Tanjung api - api Kec Talang
kelapa Banvuasin
Project Name: Indonesia XLSMART Network Consolidation Project

ASN: DRID2605230101
ASN Type: Dismantle Return

ETA: 2026-05-23

Asn Remark:

Inbound Date:

Site Code	DU Code	Subcon	Material Category	Material Model	Item Code	Item Name	Item Description	Reuse Type	Test Method	Qty	UOM	Received Qty	Picked Qty	Integrated SN	Received SN	Weight (KG)	Volume (CBM)	Remarks
SUM-SS-IDL-0128	SUM-SS-IDL-0128_MOCN_WLUB_LB	PT. Poca Jaringan Solusi	RAN	Optic Cable	2526960	Optical Cable/60m Conn LC-LC	Optical Cable/60m Conn LC-LC	Scrap	Others	3	PCS	✓						
SUM-SS-IDL-0128	SUM-SS-IDL-0128_MOCN_WLUB_LB	PT. Poca Jaringan Solusi	RAN	Cable Power	9001382	CABLEELECTRICAL-4X50MM2 CU TWISTEDPVC INSUL	CABLEELECTRICAL-4X50MM2 CU TWISTEDPVC INSUL	Scrap	Others	10	M	✓						
SUM-SS-IDL-0128	SUM-SS-IDL-0128_MOCN_WLUB_LB	PT. Poca Jaringan Solusi	RAN	SFP	2509045	TRANSCEIVER:RTN OPTIC SFP 6.144G LC.S	TRANSCEIVER:RTN OPTIC SFP 6.144G, LC, SM.	Reusable	Others	8	PCS	✓						
SUM-SS-IDL-0128	SUM-SS-IDL-0128_MOCN_WLUB_LB	PT. Poca Jaringan Solusi	RAN	RRU 3959 900M	2510265	RRU 3959 900	RRU 3959 900	Resale	Others	3	PCS	✓						
SUM-SS-IDL-0128	SUM-SS-IDL-0128_MOCN_WLUB_LB	PT. Poca Jaringan Solusi	RAN	RF Jumper	2500977	RF Jumper 4.3-10 M to DM, 2M; RF Jumper DM to	RF Jumper 4.3-10 M to DM, 2M; RF Jumper DM to DM, SM; AISG	Scrap	Others	6	PCS	✓						

Total Volume (CBM) 0

Total Weight (KG) 0

Is there any shortage, damage, discrepancy?

No ☐ Yes ☐

If Yes, Please describe the problem.

Delivered by:

Poni Asti Satrio

Checked by:

Leonard

Signature:

[Signature]

Signature:

[Signature]

Date:

24-05-2024

Date:

25-05-26

Received by:


Leonard

Signature:

[Signature]

Date:

25-05-26



SUM-SS-IDL-0128											
All List Material											
No.	Tower ID	SOW (Dismantle / Keep / New Material)	SAP Number HANA	Material Description	Quantity	UoM	Material Condition (Pls v where		Color Material (Red, Yellow, Green)	Remark	SUB-GROUP
							Good & Complete	Damaged / Dented			
1	SUM-SS-IDL-0128	Dismantle	2519640	RRU 5865 1800 Include Connector & Bracket	4	Pcs			Green	Phase 1	RRU
2	SUM-SS-IDL-0128	Dismantle	2510265	RRU 3959 900 Include Connector & Bracket	3	Pcs			Yellow	Phase 2	RRU
3	SUM-SS-IDL-0128	Dismantle	2529136	Power Cable <i>TWET</i>	10	Meter			Red	140 Phase 1 , 210 Phase 2	Cable
4	SUM-SS-IDL-0128	Dismantle	2526960	Optical Cable	3	Pcs			Red	2 Phase 1 , 3 Phase 2	Optic Cable
5	SUM-SS-IDL-0128	Dismantle	2500977	JUMPER_RF	6	Pcs			Red	16 Phase 1 , 6 Phase 2	RF Jumper
6	SUM-SS-IDL-0128	Dismantle	2527159	SFP 10G+1.4Km	8	Pcs			Green	Phase 1	SFP
7	SUM-SS-IDL-0128	Dismantle	2509045	TRANSCEIVER:RTN OPTIC SFP 6.144G,LC,SM,>	8	Pcs			Green	Phase 2	SFP

Peru ALO Supurra



24-05-2024

Leonardo LOGISTIK UTAMA
PRES
Division



25-05-2024

No Document	TSSR-50461				
RTL		Tower ID	SUM-SS-IDL-0128	Site ID	SUM-SS-IDL-0128
Site Name	LOROK OGAN ILIR	Site Topology	CORE	Approved	Anton Situmorang
Indoor / Outdoor	Indoor	FLM Cluster	INDRALAYA XL	Morphology	RURAL
Site Type	Macro	Project Name	MOCN	Province	Sumatera Selatan
Kabupaten	Ogan Ilir	Kecamatan	Indralaya Utara	Latitude	-3.1813125
Longitude	104.5686875	Zona	2_South Sumatera	Date Dismantle	2025-09-17
Vendor	Huawei	Date TSSR	2025-09-11 18:32:18	Approve Date	2025-09-23 11:37:41
LDM By	HWI.Wahyuni Rizky Perdani	LDM Date	2025-09-23 05:34:57	Plan Dismantle	2025-09-01

No	Material Simplify	Material Detail	Description	Quantity LDM	UOM	Remark	Color
1	2500977	2500977	JUMPER_RF	4	Pcs	#1	Red
2	2519640	2519640	RRU 5865 1800	2	Pcs	#2	Green
3	2526960	2526960	Optical Cable	2	Meter	#3	red
4	2527159	2527159	SFP 10G+1.4Km	4	Pcs	#4	Yellow
5	2529116	2529116	Power Cable	75	Meter	#5	red
Total				87			

Prepared by,

Approved by,

Reviewed by,

Checked by,

Received by,

HWI.Wahyuni Rizky Perdani

Anton Situmorang


(Pem. Asst. Gubernur)


(Leonard)


(25-05-26)
LOGISTIK UTAMA
Division