

No Document	TSSR-69721				
RTL		Tower ID	SUM SS SKY-0694	Site ID	SUM-SS-SKY-0694
Site Name	Tanjung Kerang Muba	Site Topology	Fiber End Site - High Risk	Approved	Anton Situmorang
Indoor / Outdoor	Outdoor	FLM Cluster	BETUNG	Morphology	RURAL
Site Type	Macro	Project Name	MOCN	Province	Sumatera Selatan
Kabupaten	Musi Banyuasin	Kecamatan	Babat Supat	Latitude	-2.7929375
Longitude	104.1369375	Zona	2_South Sumatera	Date Dismantle	
Vendor	Huawei	Date TSSR	2025-09-22 10:40:47	Approve Date	2025-10-14 12:17:10
LDM By	HWI.Wahyuni Rizky Perdani	LDM Date	2025-10-14 10.24.35	Plan Dismantle	2025-10-07

No	Material Simplify	Material Detail	Description	Quantity LDM	UOM	Remark	Color
1	2507760	2507760	UMPTb1	1	Pcs	#1	Yellow
2	2510265	2510265	RRU 3959 900	3	Pcs	INTERIM#1	Yellow
3	2529116	2529116	Power Cable	216	Meter	INTERIM#2	red
4	2526960	2526960	Optical Cable	3	Pcs	INTERIM#3	red
5	2500977	2500977	JUMPER RF	6	Pcs	INTERIM#4	Red
6	2509045	2509045	TRANSCEIVER:RTN OPTIC SFP 6.144G,LC,SM,>	6	Pcs	INTERIM#5	Green
7	2513383	2513383	R4850G	3	Pcs	#2	Yellow
8	2531609	2531609	Power#Subrack# EPW30-48A#Huawei	1	Pcs	#3	Yellow
Total				239			

Prepared by,

Approved by,

Reviewed by,

Checked by,


Received by,

HWI.Wahyuni Rizky Perdani

Anton Situmorang


(Rizky)
14-10-25.


(SEPTA)
14.10.2025


(Fadli)
14.10.2025
K.PRES

Dismantle Receive Note



DRID2510140017

Receive WH: ID XLS PLB
 Project 55A0R9P
 Code:
 ETA: 2025-10-14

Receive WH Address: Jalan Palembang Tanjung api - api Kec Lalang
 Project kelana Ranuwasin
 Name: Indonesia XLSMART Network Consolidation Project

ASN: DRID2510140017
 ASN Type: Dismantle Return
 Inbound Date:

Site Code	DU Code	Subcon	Material Category	Material Model	Item Code	Item Name	Item Description	Rouse Type	Test Method	Qty	UOM	Received Qty	Picked Qty	Integrated SN	Received SN	Weight (KG)	Volume (CBM)	Remarks
SUN-SS-SK-084	084 MDON	PT. Pika Jaringan Solusi	RAN	Modul BBU	2507780	UMPTb1	umptb1	Resale	Others	1	PCS	✓						
Total Volume (CBM)			0			Total Weight (Kg)			0									

Is there any shortage, damage, discrepancy? No ☐ Yes ☐

If Yes, Please describe the problem: _____

Delivered by: *[Signature]*
 Signature: *[Signature]*
 Date: 14-10-25

Checked by: *[Signature]*
 Signature: *[Signature]*
 Date: 14.10.2025

Received by: *[Signature]*
 Signature: *[Signature]*
 Date: 14-10-2025

Document	INBOUND		
Reference Number	SUM-SS-SKY-0694 / SUM-SS-SKY-0694	Inbound By	HWI.Sonny Susanto
Vendor	Huawei	Warehouse	HWI_Palembang
Inbound date	2025-10-14	Project	MOCN
Comment		Inbound Status	Full Site

No	Material Simplify	Material Detail	Description	Quantity LDM	Quantity Inbound	UOM	Remark	Color
1	2507780	2507780	UMPTb1	1	1	Pcs	#1	Yellow
2	2510265	2510265	RRU 3959 900	3	0	Pcs	INTERIM#1	Yellow
3	2529116	2529116	Power Cable	216	0	Meter	INTERIM#2	red
4	2526960	2526960	Optical Cable	3	0	Meter	INTERIM#3	red
5	2500977	2500977	JUMPER_RF	6	0	Pcs	INTERIM#4	Red
6	2509045	2509045	TRANSCEIVER:RTN OPTIC SFP 6.144G,LC,SM,>	6	0	Pcs	INTERIM#5	Green
7	2513383	2513383	R4850G	3	0	Pcs	#2	Yellow
8	2531609	2531609	Power#Subrack# EPW30-48A#Huawei	1	0	Pcs	#3	Yellow
Total				239	1			

Received by,

(HWI.Sonny Susanto)