

Dismantle Receive Note



DRID2604110032

Receive WH: ID XLS PLB

Project 56A0R9P
Code:

ETA: 2026-04-11

Receive WH Address: Jalan Palembang Tanjung api - api Kec Ialang
kelana Banvuasin
Project Name: Indonesia XLSMART Network Consolidation Project

Asn Remark:

ASN: DRID2604110032

ASN Type: Dismantle Return

Inbound Date:

Site Code	DU Code	Subcon	Material Category	Material Model	Item Code	Item Name	Item Description	Reuse Type	Test Method	Qty	UOM	Received Qty	Picked Qty	Integrated SN	Received SN	Weight (KG)	Volume (CBM)	Remarks
SUM-SS-IDL-1214	SUM-SS-IDL-1214_MOCN_WLUB_LB	PT. Poca Jaringan Solusi	RAN	Optic Cable	2526960	Optical Cable 60m Conn LC-LC	Optical Cable 60m Conn LC-LC	Scrap	Others	3	PCS	✓						
SUM-SS-IDL-1214	SUM-SS-IDL-1214_MOCN_WLUB_LB	PT. Poca Jaringan Solusi	RAN	Cable Power	9001382	CABLEELECTRICAL:4X50 MM2 CU TWISTEDPVC INSUL	CABLEELECTRICAL:4X50MM2 CU TWISTEDPVC INSUL	Scrap	Others	156	M	✓						
SUM-SS-IDL-1214	SUM-SS-IDL-1214_MOCN_WLUB_LB	PT. Poca Jaringan Solusi	RAN	RRU 5909 900M	2517203	RRU 5909 900	RRU 5909 900	Resale	Others	3	PCS	✓						
SUM-SS-IDL-1214	SUM-SS-IDL-1214_MOCN_WLUB_LB	PT. Poca Jaringan Solusi	RAN	SFP	2527159	SFP 10G+1.4Km	SFP 10G+1.4Km	Resale	Others	6	PCS	✓						
SUM-SS-IDL-1214	SUM-SS-IDL-1214_MOCN_WLUB_LB	PT. Poca Jaringan Solusi	RAN	RF Jumper	2500977	RF Jumper 4.3-10 M to DM, 2M; RF Jumper DM to DM, 5M; AISG	RF Jumper 4.3-10 M to DM, 2M; RF Jumper DM to DM, 5M; AISG	Scrap	Others	6	PCS	✓						

Total Volume (CBM) 0

Total Weight (KG) 0

Is there any shortage, damage, discrepancy?

No ☐ Yes ☐

If Yes, Please describe the problem. _____

Delivered by: *Reky*

Signature: *[Signature]*

Date: 11-04-26

Checked by: *Leonardo*

Signature: *[Signature]*

Date: 11-04-26

Received by: *Leonardo*

Signature: *[Signature]*

Date: 11-04-26

SUM-SS-IDL-1214											
All List Material											
No.	Tower ID	SOW (Dismantle / Keep / New Material)	SAP Number HANA	Material Description	Quantity	UoM	Material Condition (Pls v where applicable)		Color Material (Red, Yellow, Green)	Remark	SUB-GROUP
							Good & Complete	Damaged / Dented			
1	SUM-SS-IDL-1214	Dismantle	2507784	BBU3900	1	Pcs			Yellow	phase 1	BBU
2	SUM-SS-IDL-1214	Dismantle	2507780	UMPTb1	1	Pcs			Yellow	phase 1	Module BBU
3	SUM-SS-IDL-1214	Dismantle	2506926	UBBPd3	1	Pcs			Yellow	phase 1	Module BBU
4	SUM-SS-IDL-1214	Dismantle	2517203	RRU 5909 900 Include Connector & Bracket	1	Pcs			Yellow	phase 2	RRU
5	SUM-SS-IDL-1214	Dismantle	2529116	Power Cable	1	Meter			Red	phase 2	Cable
6	SUM-SS-IDL-1214	Dismantle	2526960	Optical Cable	1	Pcs			Red	phase 2	Optic Cable
7	SUM-SS-IDL-1214	Dismantle	2506977	JUMPER RF	1	Pcs			Red	phase 2	RF Jumper
8	SUM-SS-IDL-1214	Dismantle	2527159	SFP 10G+1.4Km	1	Pcs			Green	phase 2	SFP
9	SUM-SS-IDL-1214	Dismantle	2531609	PowerSubrack# EPF30-48A#Huawei	1	Pcs			Yellow	phase 1	Power rack (subrack)
10	SUM-SS-IDL-1214	Dismantle	2513383	R48500	1	Pcs			Yellow	phase 1	Rectifier

Replay

11-04-26



No Document	TSSR-26794				
RTL		Tower ID	SUM-SS-IDL-1214	Site ID	SUM-SS-IDL-1214
Site Name	SERI BANDING	Site Topology	END SITE	Approved	Cecep Supriyadi
Indoor / Outdoor	Outdoor	FLM Cluster	INDRALAYA XL	Morphology	RURAL
Site Type	MACRO	Project Name	MOCN	Province	Sumatera Selatan
Kabupaten	Ogan Ilir	Kecamatan	Pemulutan Barat	Latitude	-3.2014277777778
Longitude	104.73581944444	Zona	2_South Sumatera	Date Dismantle	2025-09-09
Vendor	Huawei	Date TSSR	2025-06-17 16:36:30	Approve Date	2025-09-09 02:48:50
LDM By	HWI.Wahyuni Rizky Perdani	LDM Date	2025-09-09 02:20:18	Plan Dismantle	2025-08-11

No	Material Simplify	Material Detail	Description	Quantity LDM	UOM	Remark	Color
1	2507784	2507784	BBU3900	1	Pcs	#1	Yellow
2	2507780	2507780	UMPTb1	1	Pcs	#2	Yellow
3	2506926	2506926	UBBPd3	1	Pcs	#3	Yellow
4	2531609	2531609	Power#Subrack# EPW30-48A#Huawei	1	Pcs	#4	Yellow
5	2513383	2513383	R4850G	2	Pcs	#5	Yellow
Total				6			

Prepared by,

Approved by,

Reviewed by,

Checked by,

Received by,

HWI.Wahyuni Rizky Perdani

Cecep Supriyadi


 (Reky)


 (Leonard)


 (2024-09-26)
 Project Division
 PRESINDO LOGISTICS