

Dismantle Receive Note



DRID2604140172

Receive WH: ID XLS PLB

Project 56A0R9P

Code:

ETA: 2026-04-14

Receive WH Address:

Project Name:

Asn Remark:

Jalan Palembang Tanjung api - api Kec Lalang
kelapa Bantuasari
Indonesia XLSMART Network Consolidation Project

ASN:

DRID2604140172

ASN Type:

Dismantle Return

Inbound Date:

Site Code	DU Code	Subcon	Material Category	Material Model	Item Code	Item Name	Item Description	Reuse Type	Test Method	Qty	UOM	Received Qty	Picked Qty	Integrated SN	Received SN	Weight (KG)	Volume (CBM)	Remarks
SUM-SS-MBL-1383	SUM-SS-MBL-1383_MOCN W/LIA LR	PT. Poca Jaringan Solusi	RAN	RF Jumper	2500977	RF Jumper 4.3-10 M to DM, 2M; RF Jumper DM to DM 5M AISG	RF Jumper 4.3-10 M to DM, 2M; RF Jumper DM to DM 5M AISG	Scrap	Others	6	PCS	✓						
SUM-SS-MBL-1383	SUM-SS-MBL-1383_MOCN W/LIA LR	PT. Poca Jaringan Solusi	RAN	RRU 5909 900M	2517203	RRU 5909 900	RRU 5909 900	Resale	Others	3	PCS	✓						
SUM-SS-MBL-1383	SUM-SS-MBL-1383_MOCN W/LIA LR	PT. Poca Jaringan Solusi	RAN	SFP	2527159	SFP 10G+1.4Km	SFP 10G+1.4Km	Resale	Others	6	PCS	✓						
SUM-SS-MBL-1383	SUM-SS-MBL-1383_MOCN W/LIA LR	PT. Poca Jaringan Solusi	RAN	Cable Power	9001382	CABLEELECTRICAL:4X50MM2 CU TWISTEDPVC INSUL	CABLEELECTRICAL:4X50MM2 CU TWISTEDPVC INSUL	Scrap	Others	123	M	✓						
SUM-SS-MBL-1383	SUM-SS-MBL-1383_MOCN W/LIA LR	PT. Poca Jaringan Solusi	RAN	Optic Cable	2526960	Optical Cable 60m Conn LC-LC	Optical Cable 60m Conn LC-LC	Scrap	Others	3	PCS	✓						

Total Volume (CBM) 0

Total Weight (KG) 0

Is there any shortage, damage, discrepancy?

No ☐ Yes ☐

If Yes, Please describe the problem.

Delivered by: Refky

Signature:

Date:

14-04-26

Checked by: Leonardo

Signature:

Date:


14-04-26

Received by: Leonardo

Signature:

Date:

14-04-26



SUM-SS-MBL-1383											
All List Material											
No.	Tower ID	SOW (Dismantle / Keep / New Material)	SAP Number HANA	Material Descption	Quantity	UoM	Material Condition (Pls v where applicable)		Color Material (Red, Yellow, Green)	Remark	SUB-GROUP
							Good & Complete	Damaged / Dented			
1	SUM-SS-MBL-1383	Dismantle	2517203	RRU 5909 900 Include Connector & Bracket	3	Pcs			Yellow	phase 2	RRU
2	SUM-SS-MBL-1383	Dismantle	252936	Power Cable twist	253	Meter			Red	phase 2	Cable
3	SUM-SS-MBL-1383	Dismantle	2526960	Optical Cable	3	Pcs			Red	phase 2	Optic Cable
4	SUM-SS-MBL-1383	Dismantle	2500977	JUMPER_RF	6	Pcs			Red	phase 2	RF Jumper
5	SUM-SS-MBL-1383	Dismantle	2527159	SFP 10G+1.4Km	6	Pcs			Green	phase 2	SFP

[Signature]

Refkey

14-04-26



No Document	TSSR-27001				
RTL		Tower ID	SUM-SS-MBL-1383	Site ID	SUM-SS-MBL-1383
Site Name	PURWODADI_MUSI RAWAS	Site Topology	END SITE	Approved	Ilhamsyah Putra
Indoor / Outdoor	Outdoor	FLM Cluster	LUBUK LINGGAU 2 XL	Morphology	RURAL
Site Type	MACRO	Project Name	MOCN	Province	Sumatera Selatan
Kabupaten	Musi Rawas	Kecamatan	Purwodadi	Latitude	-3.1073125
Longitude	103.0123125	Zona	2_South Sumatera	Date Dismantle	2026-04-14
Vendor	Huawei	Date TSSR	2025-06-17 16:36:32	Approve Date	2026-04-17 18:53:36
LDM By	HWI.Shangruijun	LDM Date	2026-04-15 16:33:19	Plan Dismantle	2026-04-06

No	Material Simplify	Material Detail	Description	Quantity LDM	UOM	Remark	Color
1	2517203	2517203	HADRWARE_RRU5909 900 MHZ	3	Pcs	phase 2#1	Yellow
2	9001382	9001382	CABLEELECTRICAL:4X50MM2 CU TWISTEDPVC INSUL	123	Meter	phase 2#2	Red
3	2526960	2526960	Optical Cable	3	Meter	phase 2#3	Red
4	2500977	2500977	JUMPER_RF	6	Pcs	phase 2#4	Red
5	2527159	2527159	SFP 10G+1.4Km	6	Pcs	phase 2#5	Yellow
Total				141			

Prepared by,

Approved by,

Reviewed by,

Checked by,


Received by,

HWI.Shangruijun

Ilhamsyah Putra


 (Refky)


 (Leonardo)


 (Leonardo)