

Dismantle Receive Note



DRID2603090083

Receive WH: ID XLS PLB

Project 56A0R9P

Code:

ETA: 2026-03-08

Receive WH Address: Jalan Palembang Ianjung api - api Kec Ialang
kelana Banvuasin
Project Name: Indonesia XLSMART Network Consolidation Project

Asn Remark:

ASN: DRID2603090083

ASN Type: Dismantle Return

Inbound Date:

Site Code	DU Code	Subcon	Material Category	Material Model	Item Code	Item Name	Item Description	Reuse Type	Test Method	Qty	UOM	Receive d Qty	Picked Qty	Integrated SN	Received SN	Weight (KG)	Volume (CBM)	Remarks
SUM-SS-IDL-1235	SUM-SS-IDL-1235_MOCN_WLUB_LB	PT. Poca Jaringan Solusi	RAN	SFP	2527159	SFP 10G+1.4Km	SFP 10G+1.4Km	Resale	Others	1	PCS	✓						
SUM-SS-IDL-1235	SUM-SS-IDL-1235_MOCN_WLUB_LB	PT. Poca Jaringan Solusi	RAN	RRU 5909 900M	2517203	RRU 5909 900	RRU 5909 900	Resale	Others	3	PCS	✓						
SUM-SS-IDL-1235	SUM-SS-IDL-1235_MOCN_WLUB_LB	PT. Poca Jaringan Solusi	RAN	Cable Power	9001382	CABLEELEC TRICAL:4X50 MM2 CU TWISTEDPVC INSULI	CABLEELECTRICAL :4X50MM2 CU TWISTEDPVC INSULI	Scrap	Others	90	M	✓						
SUM-SS-IDL-1235	SUM-SS-IDL-1235_MOCN_WLUB_LB	PT. Poca Jaringan Solusi	RAN	RF Jumper	2500977	RF Jumper 4.3-10 M to DM, 2M; RF Jumper DM to DM 5M ATSG	RF Jumper 4.3-10 M to DM, 2M; RF Jumper DM to DM 5M ATSG	Scrap	Others	6	PCS	✓						
SUM-SS-IDL-1235	SUM-SS-IDL-1235_MOCN_WLUB_LB	PT. Poca Jaringan Solusi	RAN	Optic Cable	2526960	Optical Cable 60m Conn LC-LC	Optical Cable 60m Conn LC-LC	Scrap	Others	3	PCS	✓						

Total Volume (CBM) 0

Total Weight (KG) 0

Is there any shortage, damage, discrepancy?

No ☐ Yes ☐

If Yes, Please describe the problem. _____

Delivered by: Repty

Signature:

Date: 09-03-26

Checked by:

Signature: Eru Rizki

Date: Xpresmdo

Received by:

Signature: Eru Rizki

Date: Xpresmdo

SUM-SS-IDL-1235											
All List Material											
No.	Tower ID	SOW (Dismantle / Keep / New Material)	SAP Number HANA	Material Description	Quantity	UoM	Material Condition (Pls v where Good & Damage Completd /		Color Material (Red, Yellow, Green)	Remark	SUB-GROUP
							Good & Completd /	Damage d /			
1	SUM-SS-IDL-1235	Dismantle	2507780	UMPTb1	1	Pcs	✓		Yellow	Phase 1	Module BBU
2	SUM-SS-IDL-1235	Dismantle	2517203	RRU 5909 900 Include Connector & Bracket	3	Pcs	✓		Yellow	Phase 2	RRU
3	SUM-SS-IDL-1235	Dismantle	2529116	Power Cable	212	Meter	✓		Red	Phase 2	Cable
4	SUM-SS-IDL-1235	Dismantle	2526960	Optical Cable	3	Pcs	✓		Red	Phase 2	Optic Cable
5	SUM-SS-IDL-1235	Dismantle	2500977	JUMPER_RF	6	Pcs	✓		Red	Phase 2	RF Jumper
6	SUM-SS-IDL-1235	Dismantle	2527159	SFP 10G+1.4Km	6	Pcs	✓		Green	Phase 2	SFP
7	SUM-SS-IDL-1235	Dismantle	2531609	Power#Subrack# EPW30-48A#Huawei	1	Pcs	✓		Yellow	Phase 1	Power rack (subrack)
8	SUM-SS-IDL-1235	Dismantle	2513383	R4850G	3	Pcs	✓		Yellow	Phase 1	Rectifier



 EPU RIZKA

 XPRsmdo



 Repek

 09-03-26

No Document	TSSR-26796				
RTL		Tower ID	SUM-SS-IDL-1235	Site ID	SUM-SS-IDL-1235
Site Name	PEMULUTAN MUARA DUA	Site Topology	END SITE	Approved	Cecep Supriyadi
Indoor / Outdoor	Outdoor	FLM Cluster	PALEMBANG ULU 1 XL	Morphology	URBAN
Site Type	MACRO	Project Name	MOCN	Province	Sumatera Selatan
Kabupaten	Ogan Ilir	Kecamatan	Pemulutan	Latitude	-3.135275
Longitude	104.74920277778	Zona	2_South Sumatera	Date Dismantle	2025-09-09
Vendor	Huawei	Date TSSR	2025-06-17 16:36:30	Approve Date	2025-09-09 02:48:43
LDM By	HWI.Wahyuni Rizky Perdani	LDM Date	2025-09-09 02:22:40	Plan Dismantle	2025-08-11

No	Material Simplify	Material Detail	Description	Quantity LDM	UOM	Remark	Color
1	2507780	2507780	UMPTb1	1	Pcs	#1	Yellow
2	2506926	2506926	UBBPd3	1	Pcs	#2	Yellow
3	2531609	2531609	Power#Subrack# EPW30-48A#Huawei	1	Pcs	#3	Yellow
4	2513383	2513383	R4850G	3	Pcs	#4	Yellow
Total				6			

Prepared by,

Approved by,


Reviewed by,

Checked by,


Received by,

HWI.Wahyuni Rizky Perdani

Cecep Supriyadi


 (HWI.Wahyuni Rizky Perdani)


 (Cecep Supriyadi)


 (HWI.Wahyuni Rizky Perdani)