

Dismantle Receive Note



Receive WH: ID XLS PLB

Project 56A0R9P

Code:

ETA: 2025-10-10

Receive WH Address: Jalan Palembang Tanjung api - api Kec Ialang
kelana Banvuasin
Project Indonesia XLSMART Network Consolidation
Name: Project

ASN: DRID2510100048

ASN Type: Dismantle Return

Inbound Date:

Site Code	DU Code	Subcon	Material Category	Material Model	Item Code	Item Name	Item Description	Reuse Type	Test Method	Qty	UOM	Received Qty	Picked Qty	Integrated SN	Received SN	Weight (KG)	Volume (CBM)	Remarks
SUM-JA-BKO-0013	SUM-JA-BKO-0013_MOCN W/LUE	PT. Poca Jaringan Solusi	Power	Cable	9001382	CABLEELEC TRICAL:4X50 MM2 CU TWISTEDPVC INSIR	CABLEELECTRICAL :4X50MM2 CU TWISTEDPVC INSIR	Scrap	Others	120	M	✓						
SUM-JA-BKO-0013	SUM-JA-BKO-0013_MOCN W/LUE	PT. Poca Jaringan Solusi	Reusable		2531609	Power#Subrack# EPW30-48A#Huawei	Power#Subrack# EPW30-48A#Huawei	Resale	Others	1	PCS	✓		ES2380029906				
SUM-JA-BKO-0013	SUM-JA-BKO-0013_MOCN W/LUE	PT. Poca Jaringan Solusi	MW	SFP	2509045	TRANSCEIVER:RTN OPTIC SFP 6.144G LC-S	TRANSCEIVER:RTN OPTIC SFP 6.144G, LC, SM, >	Reusable	Others	2	PCS	✓		UAMD5J00RXX.UA M9BJ58952				
SUM-JA-BKO-0013	SUM-JA-BKO-0013_MOCN W/LUE	PT. Poca Jaringan Solusi	RAN	BBU	2510539	BBU3910	BBU3910	Reusable	Others	1	PCS	✓		2102310WYGP0G 8028112				
SUM-JA-BKO-0013	SUM-JA-BKO-0013_MOCN W/LUE	PT. Poca Jaringan Solusi	RAN	Optic Cable	2526960	Optical Cable 60m Conn LC-LC	Optical Cable 60m Conn LC-LC	Scrap	Others	2	PCS	✓						
SUM-JA-BKO-0013	SUM-JA-BKO-0013_MOCN W/LUE	PT. Poca Jaringan Solusi	Rectifier		2513383	R4850G	R4850G	Resale	Others	2	PCS	✓		2102312TCXLUP7 001255,2102312TC XLUM9002902				
SUM-JA-BKO-0013	SUM-JA-BKO-0013_MOCN W/LUE	PT. Poca Jaringan Solusi	RAN	RRU 5909 1800M	2517204	RRU 5909 1800	RRU 5909 1800	Resale	Others	2	PCS	✓						
SUM-JA-BKO-0013	SUM-JA-BKO-0013_MOCN W/LUE	PT. Poca Jaringan Solusi	RAN	RF Jumper	2500977	RF Jumper 4.3-10 M to DM, 2M; RF Jumper DM to	RF Jumper 4.3-10 M to DM, 2M; RF Jumper DM to DM, 5M; AISG	Scrap	Others	4	PCS	✓						

Total Volume (CBM) 0

Total Weight (KG) 0

Is there any shortage, damage, discrepancy?

No ☐ Yes ☐

If Yes, Please describe the problem.

Delivered by:

[Signature]

Signature:

[Signature]

Date:

10-10-25

Checked by:

[Signature]

Signature:

Date: 10-10-25

Received by:

[Signature]

Signature:

Date: 10-10-25

No Document	TSSR-64518				
RTL		Tower ID	SUM-JA-BKO-0013	Site ID	SUM-JA-BKO-0013
Site Name	Sungai Ulak Bts	Site Topology	HUT	Approved	Anton Situmorang
Indoor / Outdoor	Outdoor	FLM Cluster	BANGKO XL	Morphology	RURAL
Site Type	Macro	Project Name	MOCN	Province	Jambi
Kabupaten	Merangin	Kecamatan	Nalo Tatan	Latitude	-1.9995625
Longitude	102.2824375	Zona	2_South Sumatera	Date Dismantle	
Vendor	Huawei	Date TSSR	2025-09-22 10:32:20	Approve Date	2025-10-10 15:59:00
LDM By	HWL.Wahyuni Rizky Perdani	LDM Date	2025-10-10 14:54:54	Plan Dismantle	2025-10-03

No	Material Simplify	Material Detail	Description	Quantity LDM	UOM	Remark	Color
1	2510539	2510539	BBU3910	1	Pcs	#1	Green ✓
2	2517204	2517204	RRU 5909 1800	2	Pcs	#2	Yellow ✓
3	9001382	9001382	CABLEELECTRICAL:4X50MM2 CU TWISTEDPVC INSUL	120	Meter	#3	Red ✓
4	2526960	2526960	Optical Cable	2	Pcs	#4	red ✓
5	2500977	2500977	JUMPER_RF	4	Pcs	#5	Red ✓
6	2509045	2509045	TRANSCEIVER:RTN OPTIC SFP 6.144G,LC,SM,>	2	Pcs	#6	Green ✓
7	2510265	2510265	RRU 3959 900	3	Pcs	interim#1	Yellow ✗
8	9001382	9001382	CABLEELECTRICAL:4X50MM2 CU TWISTEDPVC INSUL	180	Meter	interim#2	Red ✗
9	2526960	2526960	Optical Cable	3	Pcs	interim#3	red ✗
10	2500977	2500977	JUMPER_RF	6	Pcs	interim#4	Red ✗
11	2527159	2527159	SFP 10G+1.4Km	6	Pcs	interim#5	Yellow ✗
12	2513383	2513383	R4850G	2	Pcs	#7	Yellow ✗
13	2531609	2531609	Power#Subrack# EPW30-48A#Huawei	1	Pcs	#8	Yellow ✗
Total				334			

Prepared by,

Approved by,


Reviewed by,

Checked by,

Received by,



Kris Erlanda
10-10-25



Kris Erlanda
10-10-25



Kris Erlanda
10-10-25

Document	INBOUND		
Reference Number	SUM-JA-BKO-0013 / SUM-JA-BKO-0013	Inbound By	HWI.Sonny Susanto
Vendor	Huawei	Warehouse	HWI_Palembang
Inbound date	2025-10-10	Project	MOCN
Comment		Inbound Status	Partial

No	Material Simplify	Material Detail	Description	Quantity LDM	Quantity Inbound	UOM	Remark	Color
1	2510539	2510539	BBU3910	1	1	Pcs	#1	Green
2	2517204	2517204	RRU 5909 1800	2	2	Pcs	#2	Yellow
3	9001382	9001382	CABLEELECTRICAL:4X50MM2 CU TWISTEDPVC INSUL	120	240	Meter	#3	Red
4	2526960	2526960	Optical Cable	2	4	Meter	#4	red
5	2500977	2500977	JUMPER_RF	4	8	Pcs	#5	Red
6	2509045	2509045	TRANSCEIVER:RTN OPTIC SFP 6.144G,LC,SM,>	4	2	Pcs	#6	Green
7	2510265	2510265	RRU 3959 900	3	0	Pcs	interim#1	Yellow
8	9001382	9001382	CABLEELECTRICAL:4X50MM2 CU TWISTEDPVC INSUL	180	0	Meter	interim#2	Red
9	2526960	2526960	Optical Cable	3	0	Meter	interim#3	red
10	2500977	2500977	JUMPER_RF	6	0	Pcs	interim#4	Red
11	2527159	2527159	SFP 10G+1.4Km	6	0	Pcs	interim#5	Yellow
12	2513383	2513383	R4850G	2	2	Pcs	#7	Yellow
13	2531609	2531609	Power#Subrack# EPW30-48A#Huawei	1	1	Pcs	#8	Yellow
Total				334	260			

Received by,

(HWI.Sonny Susanto)